




1



2



3




1


Strength of some dental materials

material	σ_{tensile} (MPa)	$\sigma_{\text{comp.}}$ (MPa)
enamel	≈ 10	≈ 400
dentine	≈ 110	≈ 300
ceramics	5-400	20-5000
porcelain	≈ 25	≈ 300
Polyethylene (high density)	≈ 30	
amalgam	30-55	200-450
PMMA	≈ 50	≈ 80
glass	$\approx 50-70$	≈ 700
gold	108	
aluminum oxide	≈ 170	≈ 2100
zirconium dioxide	≈ 250	≈ 2500
gold alloys	300-900	
Pd-Ag alloys	400-700	
Ni-Cr alloys	400-900	
Co-Cr alloys	600-800	
Ti alloys	900-1100	
carbon-fiber (61%) reinforced epoxy	≈ 1700	

5




6







7


Engineering vs. „real” system



8




Mechanism of plastic deformation in crystals:




13

Movement of dislocations








13



15

Changing the strength and plastic properties of metals






Fatigue, fatigue fracture




Persistent, repetitive load (stress)
 → structural changes
 → strength decreases

Crack formation!





21



22

21

22




23

Hardness

Resistance against plastic deformation



Mohs-scale:




24

23

24

Hardness measurement


Rockwell C Test 4940 Sy=199 ksi u=2
time = 0.0000E+00
dsf = 0.10000E+01



25

Hardness measurement


Methods of microhardness measurement



A = indentation surface
(not same as the area of the projection)


$$H = \frac{F}{A} \text{ (Pa)}$$

HB HV HK



26

Connections with strength:




Hardness of dental materials:

material	HV (MPa)	HK (MPa)
dentine	~600	~700
enamel	~3400	3400-4000
gold		60-70
acrylate	~200	~200
gold alloys	600-2500	~2000
amalgam	~1000	
Pd-Ag alloys	1400-1900	
Ni-Cr alloys	3000-4000	2000-3500
Co-Cr alloys	~4000	3000-4500
glass		~5000
porcelain	4500-7000	~6000

27

Charpy test




Impact energy = The loss of the hammer's potential energy (J)

Specific impact energy = impact energy / cross sectional area of test specimen (J/m²)

28

5. A piece of zirconia with a fracture cross-sectional area of 1 cm^2 is tested in a Charpy. The drawing shows the hammer's start and end positions. The hammer has a mass of 2 kg. Calculate the specific impact energy of zirconia!



29

29